



Model: 1275AC-865	Feb. 12, 2020
Serial #: See Affected Units	
Product Bulletin # TDS-214 v 1.0	

Obsolete TD Blower Differential Pressure Transmitter

Issue

The differential pressure transmitter (Canrig P/N: N11132) is no longer available and there are no acceptable substitutes. This pressure transmitter is used on Canrig Top Drive model 1275AC-865 to verify the top drive blower is functioning.

Affected Units

- Canrig Top Drive model 1275AC-865.
- S/N: 1322, 1341, 1349, and 1386.

Recommended Action

1. No action is required if the blower and the differential pressure transmitter are functioning properly.
2. If the differential pressure transmitter (Canrig P/ N: 11132) fails, it will have to be replaced with a differential pressure switch (Canrig P/N: N10161). The PLC program will need to be reconfigured to use the input from the differential pressure switch.
3. Contact RIGLINE 24/7™ Support to order the replacement part and receive support on the necessary PLC changes.